



1. Airflow Essentials

- ✓ Ensure clear intake and exhaust paths.
- ✓ Verify negative pressure is maintained in the mining room.
- ✓ Keep cables tidy to minimize airflow obstruction.

2. Temperature Targets

- ✓ ASIC ideal inlet temp: 60–80°F.
- ✓ Outlet temp ideally below 140°F.
- ✓ Room humidity ideally below 50%.

3. Daily Checks

- ✓ Look for consistent hashrate (no drops).
- ✓ Observe fan RPM and noise changes.
- ✓ Inspect filters for dust buildup.

